

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
09/10/2014

Document Number:
668302407

Overall Inspection:

ACTION REQUIRED

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>201602</u>	<u>319856</u>	<u>JOHNSON, RANDELL</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number: 27635
 Name of Operator: ENERGY SEARCH COMPANY
 Address: 12101 EAST 2ND AVENUE #100
 City: AURORA State: CO Zip: 80011

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Roebuck, Don		don_roebuck@msn.com	
Marisco, Joe		joemarisco@yahoo.com	

Compliance Summary:

QtrQtr: SENE Sec: 13 Twp: 1S Range: 68W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
12/16/2013	600000434	PR	SI	SATISFACTORY	P		No
05/09/2006	200095053	PR	PR	ACTION REQUIRED		Fail	No
10/16/1995	500131701	PR	PR			Pass	No

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
114363	PIT		09/23/1999		-	NORTH COLORADO BLVD	<input type="checkbox"/>
201602	WELL	PR	04/28/2013	OW	001-07005	NORTH COLORADO BLVD 1	UN <input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____ Drilling Pits: _____ Wells: _____ Production Pits: _____
 Condensate Tanks: _____ Water Tanks: _____ Separators: _____ Electric Motors: _____
 Gas or Diesel Mortors: _____ Cavity Pumps: _____ LACT Unit: _____ Pump Jacks: _____
 Electric Generators: _____ Gas Pipeline: _____ Oil Pipeline: _____ Water Pipeline: _____
 Gas Compressors: _____ VOC Combustor: _____ Oil Tanks: _____ Dehydrator Units: _____
 Multi-Well Pits: _____ Pigging Station: _____ Flare: _____ Fuel Tanks: _____

Location

Signs/Marker:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
BATTERY	SATISFACTORY			
TANK LABELS/PLACARDS	ACTION REQUIRED	East steel production tank does not have the required contents, capacity or NFPA signage	Install sign to comply with rule 210.	10/10/2014
WELLHEAD	SATISFACTORY			
CONTAINERS	ACTION REQUIRED	Various containers on location without the required contents or NFPA signage/See attached photos on last page of document	Install sign to comply with rule 210.	10/10/2014
TANK LABELS/PLACARDS	ACTION REQUIRED	West steel production tank does not have the required capacity signage	Install sign to comply with rule 210.	10/10/2014
TANK LABELS/PLACARDS	ACTION REQUIRED	Fiberglass tank, with earthen secondary containment, on the far west side of battery does not have the required contents, capacity or NFPA signage/See attached photos on last page of document	Install sign to comply with rule 210.	10/10/2014
TANK LABELS/PLACARDS	ACTION REQUIRED	Fiberglass tank, without secondary containment, just west of the two steel production tanks does not have the required contents, capacity or NFPA signage/See attached photos on last page of document	Install sign to comply with rule 210.	10/10/2014

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
UNUSED EQUIPMENT	ACTION REQUIRED	Unused equipment laying beside pumpjack - i.e., tubing	Remove unused equipment	10/10/2014

Spills:				
Type	Area	Volume	Corrective action	CA Date
PW/CO	Truck Loadout	<= 5 bbls	Remove or remediate stained soil around truck loadout valve on fiberglass tank/See attached photos on last page of document	10/10/2014
Other	Pump Jack	<= 5 bbls	Remove hardened, oil contaminated soil around pumpjack/See attached photos on last page of document	10/10/2014
PW/CO	WELLHEAD	<= 5 bbls	Remove or remediate stained soil around wellhead/See attached photos on last page of document	10/10/2014

Multiple Spills and Releases?

Fencing/:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
SEPARATOR	SATISFACTORY	Wooden fencing		
TANK BATTERY	SATISFACTORY	Wooden fencing		

Equipment:					
Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Prime Mover	1	SATISFACTORY	Electric motor		
Gas Meter Run	1	SATISFACTORY			
Horizontal Heated Separator	1	SATISFACTORY			
Pump Jack	1	SATISFACTORY			

Facilities:				
<input type="checkbox"/> New Tank	Tank ID: _____			
Contents	#	Capacity	Type	SE GPS
OTHER	1	OTHER	FIBERGLASS AST	39.967091,-104.942324
S/A/V:	Comment: Contents and capacity unknown - no signage/See attached photo on last page of document			
Corrective Action:				Corrective Date:

Paint	
Condition	
Other (Content)	_____
Other (Capacity)	_____
Other (Type)	_____

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Corrective Action	Provide proper secondary containment around tank			Corrective Date 10/10/2014
Comment	No secondary containment around tank/See attached photo on last page of document			

Facilities: New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
OTHER	1	OTHER	FIBERGLASS AST	39.967025,-104.942746
S/A/V:	Comment:		Contents and capacity unknown - no signage/See attached photo on last page of document	
Corrective Action:				Corrective Date:

Paint

Condition	
Other (Content)	_____
Other (Capacity)	_____
Other (Type)	_____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Corrective Action				Corrective Date
Comment				

Facilities: New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
OTHER	2	OTHER	STEEL AST	39.967005,-104.942622
S/A/V:	Comment:		SATISFACTORY	
Corrective Action:				Corrective Date:

Paint

Condition	Adequate
Other (Content)	_____
Other (Capacity)	_____
Other (Type)	_____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Corrective Action				Corrective Date
Comment				

Venting:

Yes/No	Comment
NO	

Flaring:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 201602

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/A/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/A/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 201602 Type: WELL API Number: 001-07005 Status: PR Insp. Status: UN

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

S/A/V: _____ CA Date: _____

CA: _____

Comment: No production records on file with COGCC since March 2013

BradenHead

Comment: **Bradenhead plumbed to surface**

CA: _____

CA Date: _____

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): N

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? **Fail** CM **Hardened, oil contaminated soil piled up on ground by pumpjack/See attached**

CA **Remove contaminated soil** CA Date **10/10/2014**

Unused or unneeded equipment onsite? **Fail** CM **Unused equipment laying on ground beside pumpjack - i.e.,**

CA **Remove unused equipment** CA Date **10/10/2014**

Pit, cellars, rat holes and other bores closed? Pass CM _____

CA _____ CA Date _____

Guy line anchors removed? Pass CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? In Production areas stabilized ? In

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? In _____
 Production areas have been stabilized? In _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation Fail

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			
Other	Pass	Other	Pass			Vegetation

S/A/V: SATISFACTOR Corrective Date: _____

Y

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
668302408	Energy Search - N Colorado Blvd 1 (001-07005) (1)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3430104
668302409	Energy Search - N Colorado Blvd 1 (001-07005) (2)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3430105
668302410	Energy Search - N Colorado Blvd 1 (001-07005) (3)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3430106
668302411	Energy Search - N Colorado Blvd 1 (001-07005) (4)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3430107
668302412	Energy Search - N Colorado Blvd 1 (001-07005) (5)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3430108
668302413	Energy Search - N Colorado Blvd 1 (001-07005) (6)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3430109
668302414	Energy Search - N Colorado Blvd 1 (001-07005) (7)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3430110
668302415	Energy Search - N Colorado Blvd 1 (001-07005) (8)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3430111
668302416	Energy Search - N Colorado Blvd 1 (001-07005) (9)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3430112
668302417	Energy Search - N Colorado Blvd 1 (001-07005) (10)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3430113
668302418	Energy Search - N Colorado Blvd 1 (001-07005) (11)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3430114
668302419	Energy Search - N Colorado Blvd 1 (001-07005) (12)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3430115

ACTION REQUIRED

ANY ACTION REQUIRED items listed on this report indicate that the oil and gas facility or the oil and gas operations listed on the report may be in violation of the rules and regulations of the Colorado Oil and Conservation Commission (“COGCC”) and corrective action is required.

There is reasonable cause to believe that a violation of the Oil and Gas Conservation Act, or of any rule, regulation, or order of the Commission, or of any permit issued by the Commission, has occurred. The Operator’s compliance with this Inspection Report is required to resolve these alleged violations. This document requires the Operator to timely respond to the COGCC and to comply with directives as listed by the **Corrective Action Deadline Date**. Failure to do so will result in the issuance of a Notice of Alleged Violation and initiation of enforcement proceedings in which COGCC will seek monetary penalties for the alleged violations pursuant to § 34-60-121, C.R.S. and Rule 523, COGCC Rules of Practice and Procedure, 2 CCR 404-1. (Please note that the COGCC's penalty authority was recently increased to a maximum of \$15,000 per day and penalties are no longer capped at a maximum of \$10,000 per violation.)