



Photo 1. View from northeastern corner of project area facing center.



Photo 2. View of planted trees in good condition along the southern edge of the well pad working area.



Photo 3. Minor erosion in the southeastern corner of the project area needs to be monitored.