

DE	ET	OE	ES
----	----	----	----

Replug By Other Operator

Document Number:
400697097

Date Received:

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 10110 Contact Name: Sam Bradley
 Name of Operator: GREAT WESTERN OPERATING COMPANY LLC Phone: (970) 286-3426
 Address: 1801 BROADWAY #500 Fax: _____
 City: DENVER State: CO Zip: 80202 Email: sbradley@gwogco.com

For "Intent" 24 hour notice required, Name: Johnson, Randell Tel: (303) 815-9641
COGCC contact: Email: randell.johnson@state.co.us

API Number 05-123-10372-00
 Well Name: BEIERLE Well Number: 1
 Location: QtrQtr: SENE Section: 26 Township: 1N Range: 66W Meridian: 6
 County: WELD Federal, Indian or State Lease Number: _____
 Field Name: WATTENBERG Field Number: 90750

Notice of Intent to Abandon Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.025116 Longitude: -104.738734
 GPS Data:
 Date of Measurement: 09/24/2014 PDOP Reading: 1.4 GPS Instrument Operator's Name: Derik Drinnen
 Reason for Abandonment: Dry Production for Sub-economic Mechanical Problems
 Other _____
 Casing to be pulled: Yes No Estimated Depth: _____
 Fish in Hole: Yes No If yes, explain details below
 Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below

Details: Well was originally plugged by previous operator 5/19/1982. During the fracture treatment of the J-Sand casing parted at 2,900'. The operator attempted to fix the part with an allignment tool and cement and when they drilled out cement they believe they found tubing on the outside of the casing (it is unclear if this is the allignment tool or some other fish, or an incorrect assumption). They could not get down to the perforations to adequatly plug and thus pumped a plug at the casing part, pulled 4-1/2" from 225', pumped a shoe plug, and a surface plug (see attached current WBD). This well is in proximity to the future horizontal Bierle wells Great Western plans. Please see attached documentation and comments section for the detailed re-entry and re-abandonment of the subject well.

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
J SAND	8084	8092	05/20/1982		

Total: 1 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	12+1/4	9+5/8	36	185	325	185	0	VISU
1ST	7+7/8	4+1/2	10.5&11.6	8,219	325	8,219	7,370	CBL

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth _____ with _____ sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.

CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.

CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 30 sks cmt from 8084 ft. to 8092 ft. Plug Type: CASING Plug Tagged:

Set 30 sks cmt from 2900 ft. to 2600 ft. Plug Type: CASING Plug Tagged:

Set 20 sks cmt from 185 ft. to 0 ft. Plug Type: CASING Plug Tagged:

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:

Perforate and squeeze at 7350 ft. with 150 sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at 4760 ft. with 150 sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at 1350 ft. with 375 sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set 10 sacks half in. half out surface casing from 0 ft. to 50 ft. Plug Tagged:

Set _____ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Plugging Date: _____

*Wireline Contractor: _____ *Cementing Contractor: _____

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1103 Yes No *ATTACH JOB SUMMARY

Technical Detail/Comments:

Expedited approval is requested.

Plans to re-abandon the subject well are detailed in the 'Proposed P&A WBD'. The well has been located, and GPS'd (support documentation and pictures attached). The plan is to re-install a wellhead on the surface casing and clean the well out to 225' where 4-1/2" casing was pulled from. We will then tie into the 4-1/2" casing and bring it back up to surface and install a wellhead on the 4-1/2". Then the well will be cleaned out to the part in the 4-1/2" casing at 2,902'. The possible fish in the hole will be investigated and milled up until we can re-enter the 4-1/2" casing below the part or beginning at 2,911'. We will clean out to the original J-Sand perforations that were never isolated with cement and pump 30 sx of cement into the J-Sand perfs. We will then move up hole and perf & squeeze the top of the Niobrara for isolation. We will continue moving up hole and perf and squeeze the Sussex for isolation. Finally we will move up hole to isolate the Fox Hills utilizing a perf and squeeze method. Balanced plugs will be set in the casing across the part at 2,900' and across the surface shoe.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Sam Bradley

Title: Petroleum Engineer Date: _____ Email: sbradley@gwogco.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____ Date: _____

CONDITIONS OF APPROVAL, IF ANY: _____

Expiration Date: _____

Attachment Check List

<u>Att Doc Num</u>	<u>Name</u>
400697138	WELLBORE DIAGRAM
400697140	WELLBORE DIAGRAM
400697171	LOCATION PHOTO
400698389	SURFACE OWNER CONSENT

Total Attach: 4 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>

Total: 0 comment(s)