

Island Ranch 13-796

Inspection# 675200644

Pooling of stormwater behind frac tanks and at base of cuttings.



Pooling of stormwater behind frac tanks.



Pooling water. Berm is soft and beginning to subside.



Tanks with no signage on them.



Frac tree with mandrel stored off location.



Insufficient signage at wellheads.

