



Photo 1. View of western edge of project area from northwestern corner facing southward.



Photo 2. View of northern edge of project area from northwestern corner facing eastward.



Photo 3. View of straw wattle that appears to be functioning within southern portion of project area.



Photo 4. View of woody debris placed in erosional channel which will not likely be sufficient for stormwater control.