



Photo 1. View of silt trap in good condition in northeastern corner of project area.



Photo 2. View of revegetation in eastern portion of project area.





Photo 3. View of project area from northeastern corner toward center.



Photo 4. View of deep ruts in western portion of project area.





Photo 5. View of deep ruts in western and central portion of project area.