

## **Reference Area Photographs**

**Inspection Conducted on October 18, 2014**

**Delta**

**Buzzard Creek 11-13**


**East of Colbran**

**Location ID #312614**

**API 077 08625**

**(Well P&A, Pad reclaimed)**

## Buzzard Creek 11-13



Approximately 90 feet between well location (as built coordinates) and pond.  
Pond is lower by about 9 feet than the well ground surface .



Aerial view. Well location as built.



View of the pond, on the western side of the pad.



## Buzzard Creek 11-13



Moist soil and green vegetation on the northwest corner of the pad, up-gradient of the pond. Seeps on the north and northwest sides of the pond. Very little water. No flow.



Moist soil and green vegetation on the northwest corner of the pad, up-gradient of the pond.



## Buzzard Creek 11-13



Little water at the bottom of the pond. No hydrocarbon odor or sheen.



Seeps on the northwest side of the pond.  
Some white mineral deposition.