

**Site Photos (05-055-06066) 10/30/2014**

Looking towards the East, SMU 6-15-I

photo #1



Looking Southwest where timber was cut

photo #2



**Site Photos (05-055-06066) 10/30/2014**

Looking North, wood debris remains where trees were cut

photo #3



Looking East at the West side of location near a water spring where trees were cut

photo #4



Site Photos Site Photos (05-055-06066) 10/30/2014

West side of location looking towards the Northwest

photo #5



Ground disturbance on West side of location creates erosion potential

photo #6



**Site Photos (05-055-06066) 10/30/2014**

Tree stumps pushed into a pile on the Northwest side of the location

photo #7



Ground disturbance on West side of location creates erosion potential

photo #8



**Site Photos (05-055-06066) 10/30/2014**

East side of location where timber was cut

photo #9



Ground disturbance on East side of location creates erosion potential

photo #10



**Site Photos (05-055-06066) 10/30/2014**

Ground disturbance on East side of location creates erosion potential

photo #11



Stumps pushed into a pile on the Northeast side of location

photo #12



**Site Photos (05-055-06066) 10/30/2014**

Pipeline to the Meter station has Diffuse Knapweed growth

photo #13



Knapweed is present around the Meter station

photo #14



**Site Photos (05-055-06066) 10/30/2014**

Diffuse Knapweed present along roadsides

photo #15



Noxious weed growth: Diffuse Knapweed

photo #16

