

**Site Photos: API# 05-017-06399**

**Date: November 19, 2014**



**photo 1:** Access Road to the location, facing North.



**photo 2:** Facing Northwest at the Southeast corner of the location.



**Site Photos: API# 05-017-06399**

**Date: November 19, 2014**



**photo 3:** Center of the location facing North.



**photo 4:** Center of the location facing West.



**Site Photos: API# 05-017-06399**

**Date: November 19, 2014**



**photo 5:** Center of the location facing South.



**photo 6:** Center of the location facing East.



**Site Photos: API# 05-017-06399**

**Date: November 19, 2014**



**photo 7:** Area bare of vegetation at the Northeast corner of the location.



**photo 8:** Erosion occurring at the West side of the location.



Site Photos: API# 05-017-06399

Date: November 19, 2014



**photo 9:** Wood pole and pipe with metal cage remains on location (38.97165/-103.05369).



**photo 10:** Surrounding vegetation, reference area.