

Furr22-07 (F1) Pad

Inspection# 675200928

Rutting on location.



Erosion of cut slope on south end
of location.



Unused tank to be removed.



Pipe at entrance of location to be removed.



Solar panel stand to be removed at wellheads.

