

Bosely SG 21-27

Inspection# 675200974

Stormwater drain from wellheads.



No retention pond or check at end of drain.



Erosion from drain outlet on reclaimed area.



Erosion from drain outlet on reclaimed area.



Breached area on berm on south end of location.



Debris/ Unused equipment near tank containment.

