

**SG 34-28**

Inspection# 675200993

Access road: Shoulders have been damaged from truck traffic and sediment pushed into vegetation.



Debris on location



Location the day of inspection.

