

WPX Energy

GM 44-1 Pad

Location # 324080

Unstabilized cut wall behind wells



Erosion of check dam



Erosion from discharge of check dam





12.23.2014 15:50

Erosion at culvert



Bales have been washed away



Unstable wall behind separators

