

## F 8 OU Pad

Inspection# 675201056

Access road to location was rutted  
and travel was difficult at time of  
inspection.



Entrance of location.



Rutting on location.

