

EnCana Oil and Gas

C28 Pad

Location # 335200

Run on diversion ditch is washing and traps are filling with sediment.



Run on diversion ditch is washing and traps are filling with sediment.



Low water crossing eroding on out let side



Erosion damage outlet side of low water crossing.



Erosion rills from hillside have buried
tank flow line.

