

Site Photos: API# 05-009-06124

Date: January 20, 2015



**photo 1:** Pipe riser remains near the east side of the location.



**photo 2:** East side of the location facing west. Bare areas 20'x10' and 15'x10'.



Site Photos: API# 05-009-06124

Date: January 20, 2015



**photo 3:** Oil stained soil approx. 10'x5'. Soil had a strong oil odor.



**photo 4:** Oil stained soil approx. 10'x5'. Soil had a strong oil odor.



**Site Photos: API# 05-009-06124**

**Date: January 20, 2015**



**photo 5:** Center of the location facing north.



**photo 6:** Center of the location facing west.



**Site Photos: API# 05-009-06124**

**Date: January 20, 2015**



**photo 7:** Center of the location facing south.



**photo 8:** Center of the location facing east.



**Site Photos: API# 05-009-06124**

**Date: January 20, 2015**



**photo 9:** Facing east, surrounding vegetation around the location.



**photo 10:** Facing south, surrounding vegetation around the location.