

WPX Energy

GM 33-1

Location # 324063

Build up of sediment in ditch at entrance of location



Culvert needs maintained

Sediment build up in inlet



Unable to find outlet

