

Site Photos: API# 05-043-06224

Date: February 10, 2015



photo 1: Operator/Location sign at the tank battery. Lat/Long: 38.28764/-105.10938



photo 2: Tank battery location, approximately 100yds north of the location.

Site Photos: API# 05-043-06224

Date: February 10, 2015



photo 3: Facing south towards the location.



photo 4: Well head and tank battery. No signs or markers were found required by rule 210.

Site Photos: API# 05-043-06224

Date: February 10, 2015



photo 5: Southeast corner of location facing northwest. The location has not been reclaimed.



photo 6: Southwest side of the location facing east towards the production equipment.

Site Photos: API# 05-043-06224

Date: February 10, 2015



photo 7: The area on the south side of the location has not been reclaimed and is susceptible to erosion.



photo 8: Soil stockpile at the southwest corner of the location is not stabilized.

Site Photos: API# 05-043-06224

Date: February 10, 2015



photo 9: Waddles are displaced at the north side of the location.



photo 10: Guy line anchors around the location do not have a marker.

Site Photos: API# 05-043-06224

Date: February 10, 2015



photo 11: Unused equipment/sections of pipe remain at the location.



photo 12: Facing east at the access road that goes towards the location.