

Grizzly 3-32H

Inspection# 673401785

Cuttings berm made out of
what appears to be cuttings.
Not compacted, not
continuous.

2/11/2015

Inspection 673401785



Cuttings berm made out of
what appears to be cuttings.
Not compacted.

2/11/2015

Inspection 673401785



Cuttings with no berm.

2/11/2015

Inspection 673401785



Cuttings with no berm.

Alternate location entrance
and HWY 14 visible on right
side of picture.

2/11/2015

Inspection 673401785



Cuttings berm not
compacted.

2/11/2015

Inspection 673401785



Cuttings berm not
continuous or compacted.

2/11/2015

Inspection 673401785



Cuttings berm not
continuous or compacted.

2/11/2015

Inspection 673401785



Cuttings berm not
continuous or compacted.

2/11/2015

Inspection 673401785



Waddles falling into culvert
at entrance to location.

2/11/2015

Inspection 673401785



Waddles falling into culvert
at entrance. Cuttings in a
non continuous/compacted
berm visible behind ditch.
Ditch runs along HWY 14.

2/11/2015

Inspection 673401785



Cuttings berm not
continuous or compacted.

7/24/2014

Inspection 673400878



Cuttings berm not
compacted.

7/24/2014

Inspection 673400878



Cuttings berm not
compacted. Cuttings
spilling over berm.

7/30/2014

Inspection 673400947



Cuttings berm and
perimeter berm not
compacted.

7/30/2014

Inspection 673400947

