

## Grizzly 3-32H

Inspection# 673401899

Oily fluid in pump house.

3/10/2015

Inspection 673401899



Stained soil, oil in water  
outside of berm.

3/10/2015

Inspection 673401899



Product outside of berm  
mixing with stormwater.

3/10/2015

Inspection 673401899



Contaminated soil bermed  
with and by cuttings.

3/10/2015

Inspection 673401899





Contaminated soil bermed  
with and by cuttings.

2/11/2015

Inspection 673401785



Contaminated soil with  
fluid.

3/10/2015

Inspection 673401899



Contaminated soil with  
fluid.

2/11/2015

Inspection 673401785



Contaminated soil with  
fluid.

3/10/2015

Inspection 673401899





Contaminated soil with sheen.

2/11/2015

Inspection 673401785



Cuttings with no berm.

3/10/2015

Inspection 673401899



Cuttings with no berm.

2/11/2015

Inspection 673401785



Cuttings with no berm.

3/10/2015

Inspection 673401899





Cuttings with no berm.

2/11/2015

Inspection 673401785



Waddles blocking culvert  
at entrance.

3/10/2015

Inspection 673401899



Waddles blocking culvert at  
entrance.

3/10/2015

Inspection 673401899



Waddles falling into culvert  
at entrance.

2/11/2015

Inspection 673401785





Waddles falling into culvert  
at entrance.

2/11/2015

Inspection 673401785



Vehicle tracking off of  
location.

3/10/2015

Inspection 673401899

