

Antero Lundgren A-1 Location ID# 324342 (Lundgren Frac/Flowback Pit, #149019)



Viewing south: Frac/Flowback pit.



Viewing East: Frac/Flowback pit



Viewing northeast: Frac/Flowback pit



Viewing north & downgradient of Frac/Flowback pit: Pre-existing salvaged irrigation diversion ditch & pit's southern fill slope.

Antero Lundgren A-1 Location ID# 324342 (Lundgren Frac/Flowback Pit, #149019)



Viewing northwest from pit area: Lundgren Well Pad with stockpiled E&P waste.



Viewing west: E&P Landfarm strip and adjacent berm & ditch stormwater BMPs.



View of cellar-enclosed Shut-in well (Lundgren A-1# 045-11276).



Viewing East : open receptacles containing miscellaneous debris: weeds, dirt, oily debris & stormwater.

Antero Lundgren A-1 Location ID# 324342 (Lundgren Frac/Flowback Pit, #149019)



Google Earth: 2011 Aerial Image

Antero Lundgren A-1 Location ID# 324342 (Lundgren Frac/Flowback Pit, #149019)



COGS GIS: 2009 Aerial Image