

WPX Energy

PA 24-34 Production Facility

Location # 334989

Subsidence of buried culvert



Rill running along bale into ditch



Erosion ditch at culvert outlet



Sink hole on ditch wall



03.20.2015 14:18