

WPX Energy

ARCO-66S96W 31 SENE

Location # 335222

Stain around well.



Stain around well.



Unstable cut slope behind separators.



Erosion of cut slope behind separators and sediment build up.



Ditch down the corner of location entrance.

Sediment built up before check dam



Erosion of road cutting into ditch

