



Photo 1. View of rill erosion from what appears to be stormwater flows exiting the southern edge of the working area of the well pad.



Photo 2. View of erosional channel from well pad (approximately two feet wide and two feet deep that is flowing toward pond and wetland southeast of project area.



Photo 3. View of erosional channel (approximately 1 to 2 feet wide and 1 foot deep) from well pad flowing toward wetland complex east of well pad.



Photo 4. View of erosional channel on eastern edge of project area.