



Photo 1. Area in southern portion of project area that is approximately 15 feet wide by 50 feet long needing revegetation.



Photo 2. View of kochia seedlings and kochia debris in area needing revegetation within the southern portion of project area.





Photo 4. View of rill erosion from stormwater flows exiting the southern edge of the working area.



Photo 5. View of project area from northeastern corner facing center. Good revegetation throughout much of the project area.