



photo 1: Facing northwest towards the location. Equipment is on-site to begin the project.



photo 2: Facing north towards the location. Equipment beginning to mobilize to start the project.



photo 3: Top soil pile located at the east side of the location



photo 4: Facing west towards the south side of the location. Perimeter of the location is fenced.



photo 5: Silt fence installed around the west side of the location.



photo 6: Facing east, silt fence has been installed prior to excavation operations.



photo 7: Beginning of the excavation operation to re-contour the location.



photo 8: Bottom, center of the photo where cellar rings existed.



photo 9: Facing north, beginning of the excavation operation to re-contour the location.



photo 10: Facing southeast on the location towards the access road.



photo 11: Beginning of the access road facing southwest.



photo 12: Access road west towards the location which will be re-contoured.



photo 13: Facing northwest towards the location.



photo 14: Spill kit (yellow barrel) at the bottom of the access road.



photo 15: Facing north at the material that has been pushed up for recontouring.



photo 16: Facing north towards the north side of the location.



photo 17: Facing south along thwe west side of the location.



photo 18: West side of the location where silt fence is preventing sediment from running off site.



photo 19: Cellar ring has been removed. Conductor pipe found about 5ft. below the surface.



photo 20: Center of the location where 4 cellar rings have been removed.