



**photo 1:** Facing east towards the location which has no vegetation growth where soils are compacted.



**photo 2:** Facing north at the center of the location.





**photo 3:** Facing south at the center of the location.



**photo 4:** Facing west at the center of the location.





**photo 5:** Soil de-compaction in areas where vegetation will not grow.



**photo 6:** Compacted soils being excavated with a backhoe to break up the compacted soils.





**photo 7:** Facing east towards areas which were decompacted with the backhoe.



**photo 8:** Harrowing the decompacted areas with the atv.





**photo 9:** Bare areas were decompacted, fertilized, and seeded.



**photo 10:** Bare areas were spread with wood mulch.





**photo 11:** Areas bare of vegetation covered with wood straw mulch approx 50% coverage.



**photo 12:** West side of the location facing east.





**photo 13:** West side of the location facing north east.



**photo 14:** Upon completion the fence where the site was accessed was properly fixed.