

Bosely SG 24-22 (5/11/15)

Inspection# 675201539

Sediment run on in NE
corner of location.



Sediment run on from NE
corner of location.



Sediment run on in NE corner of location and erosion channel.



Erosion under rip rap outlet of retention pond.



Erosion at culvert outlet.

39.41736/-108.09930



Sediment run on to road.

Noted on previous
inspection.

39.41645/-108.09816



Sediment run on to road.
Noted on previous
inspection.

39.41645/-108.09816



Erosion of road across from
sediment run on. Noted on
previous inspection.



Sediment run on along
access road. Noted on
previous inspection.

