

Bosely SG 21-27 (5/11/15)

Inspection# 675201541

Breached berm at initial inspection. 12/19/14



Breached berm at follow up inspection. 5/11/15



There is sediment movement down gradient from breached berm into vegetation at the follow up inspection. Not visible at initial inspection because of snow cover.



BMPs have been added to area of erosion as requested on previous inspection.

