



photo 1: Well sign, Crum 33-5V



photo 2: Southeast corner of the location facing northwest.



photo 3: Base of the pad at the east side of the location.



photo 4: Metal tin debris near the pit. Shed panels appear to be leaning.



photo 5: North side of the location area in photo has little to no vegetation growth.



photo 6: The northwest Guyline anchor is not properly marked.