



Photo 1. View of northeastern portion of project area from northern edge of interim reclamation area facing southwestward.



Photo 2. View of interim reclamation area and well pad from northern edge of project area facing southward.





Photo 3. View of northeastern and eastern portion of interim reclamation area from northern edge facing southeastward.



Photo 4. View of flowline from the access road facing east-northeastward. Grass species are not in identifiable condition.





Photo 5. View of hydromulch being applied to the northern edge of the access road.