



Photo 1. Southern portion of project area from southern edge of working area facing westward.



Photo 2. View of flowline disturbance from southwestern corner of well pad that is vegetated with weeds.



Photo 3. View of straw wattles in western portion of project area.



Photo 4. View of western portion of project area from southwestern corner facing northward.



Photo 5. View of northern portion of project area from northwestern corner facing eastward.



Photo 6. View of cut-slope in eastern portion of project area with no stormwater controls.