



Surface
Drainage
Indiscernible


BH03	
Compound (ug/L)	4/9/2015
Benzene	<1.0
Toluene	<1.0
Ethylbenzene	<1.0
Total Xylenes	<1.0

BH02	
Compound (ug/L)	4/9/2015
Benzene	<1.0
Toluene	<1.0
Ethylbenzene	<1.0
Total Xylenes	<1.0

BH01	
Compound (ug/L)	4/9/2015
Benzene	3.0
Toluene	<1.0
Ethylbenzene	<1.0
Total Xylenes	<1.0

BH04	
Compound (ug/L)	4/9/2015
Benzene	<1.0
Toluene	<1.0
Ethylbenzene	<1.0
Total Xylenes	<1.0

BH05	
Compound (ug/L)	4/9/2015
Benzene	<1.0
Toluene	<1.0
Ethylbenzene	<1.0
Total Xylenes	1.0



Agriculture

Access Road

- LEGEND
- Approximate Area of Excavation
 - Monitoring Well Location
 - Remediation Pipe
 - Groundwater Sample Location

FIGURE 3
GROUNDWATER
ANALYTICAL RESULTS

DRAWN BY: ESS

DATE: 5/14/2015

Facility Diagram
PDC Energy, Inc. – DJ Basin
Miller GJ 33-24
NWSE S24 T6N R65W
Weld County, CO

 **TASMAN**
GEOSCIENCES 6899 Pecos Street, Unit C
Denver, CO 80221