



Photo 1. View of rill erosion in western portion of project area, downslope of straw wattles. Vegetation in foreground is largely Russian thistle (*Salsola tragus*).



Photo 2. View of more rills in western portion of project area, facing downslope. Green vegetation is Russian thistle seedlings.



Photo 3. View of more rills coming off of western edge of project area facing downslope.



Photo 4. Birdseye view of vegetation within western portion of reclaimed area. Vegetation is largely Russian thistle.



Photo 5. View of western portion of project area from southwestern corner facing northward. Vegetation is largely Russian thistle with scattered grass seedlings and other ruderal vegetation.



Photo 6. View of large working area from northeastern corner facing southwestward.



Photo 7. View of eastern portion of working area from northeastern corner facing southward.



Photo 8. View of cut-slope in eastern portion of project area from northeastern corner facing south-southeastward.



Photo 9. View of unvegetated flowline. Vegetation in flowline is nearly 100 percent cheatgrass (*Bromus tectorum*). Cropland vegetation can be seen on both sides of flowline.