



Photo 1. View of project area from northwestern corner facing center.



Photo 2. View of stormwater containment in southeastern corner of well pad. This needs to be monitored carefully and deepened and/or reinforced if stormwater continues to accumulate here.



Photo 3. View of irrigation ditch in northwestern corner of project area facing southward.



Photo 4. View of topsoil stockpile within western portion of project area facing northward.



Photo 5. View of eastern edge of project area from southeastern corner facing northward. Perimeter straw wattles appear to be effectively filtering stormwater flows at this time.



Photo 6. View of southern edge of project area from southeastern corner facing westward. Perimeter straw wattles appear to be effectively filtering stormwater flows at this time.



Photo 7. View of northern edge of project area from northeastern corner facing westward.



Photo 8. View of culvert inlet along access road. Sediment is accumulating in the inlet basin and will soon need maintenance.