



**photo 1:** Prior to reclamation activities facing southwest off of the main access road.



**photo 2:** Facing west along the the recontoured access road to the Arroyo 9-16.





**photo 3:** Facing northwest towards the location prior to reclamation activities.



**photo 4:** Facing east from the southwest corner of the location.





**photo 5:** Facing northeast from the southwest corner of the location.



**photo 6:** Facing east towards the location.





**photo 7:** Reclamation activities beginning with fertilizer application.



**photo 8:** The location was then disced to incorporate the fertilizer and prepare the soil for seeding.





**photo 9:** Broadcast seeding was then performed throughout the location.



**photo 10:** Following seeding, a harrow was used to ensure proper seed soil contact.





**photo 11:** A jute blanket was installed at the north side of the location.



**photo 12:** All disturbed areas of the location were then mulched with certified hay.





**photo 13:** Northeast corner of the location facing south.



**photo 14:** Northeast corner of the location facing southwest.





**photo 15:** Southwest side of the location facing northeast.



**photo 16:** Southeast corner of the location facing northwest.