

## A.P. Urie 1

Inspection# 673402259

Overview of spill area looking east. Breach of berm at base visible in right foreground. Breach of berm with overflow and resultant spill path visible in left background.



Overview of spill looking south. Berm overflow and spill path visible in foreground.





Close-up of berm overflow area on north side of tank/location. Liquid visible is oil.



View from terminus of spill pathway approximately 50 feet from edge of berm looking west. Greatest concentration of material appears to be immediately outside of berm.





Stained soil inside berm on  
south side of tank/location.  
Incomplete tank labels.



Close-up of pooled  
hydrocarbons inside berm  
on north side of  
tank/location.





Pooled hydrocarbons outside of berm at beginning of spill pathway on north side of tank/location.



Stained soil at wellhead.  
Unclosed rathole in foreground on left.



Location overview.  
Incomplete battery sign, no  
wellhead sign, unclosed  
rathole, gravel piles with  
no containment, debris,  
weeds and spill.

