



photo 1: Traveling northwest along the main access road.



photo 2: Traveling west along the main access road.



photo 3: Traveling west along the main access road.



photo 4: Facing back northeast along the main access road.



photo 5: Traveling southeast along the main access road. Area of concern of the complainant.



photo 6: Facing south along the main access road. Area of concern of complainant due to potential water pooling.



photo 7: Facing south along the main access road. Area of concern of complainant due to potential lack of gravel.



photo 8: : Facing south along the main access road.



photo 9: Facing west along the main access road. Area of concern of the complainant.



photo 10: Along the main access road. Area of concern of complainant due to potential water pooling.



photo 11: Facing southeast along the main access road.



photo 12: Along the main access road. Area of concern of complainant due to potential water pooling.



photo 13: Facing southeast along the main access road.



photo 14: Facing southeast along the main access road.



photo 15: Facing north towards the well location.



photo 16: Well sign. Talon 34-25