



Photo 1. View of location from SW corner looking North , showing Spotted Knapweed.

July 23,2015

Inspection Photos API# 045-13420 loc#  
334747





Photo 2. View from NW corner of pad looking down at wattles needing maintenance.

July 23, 2015

Inspection Photos API# 045-13420 loc#  
334747



Photo 3. View of location from NW corner below berm, looking up at erosion from stormwater run off from pad.





Photo 4. View of access road from SW corner of Location looking at sediment run off .

July 23,2015

Inspection Photos API# 045-13420 loc#  
334747