



Spotted Knapweed infesting Interim reclamation areas of location.

June 23, 2015

Inspection Photos API# 045-07245 Loc #  
334572



Looking East at access road immediate to Location entrance, in need of maintenance.

June 23, 2015

Inspection Photos API# 045-07245 Loc #  
334572