



Photo # 1: Center of Pad, which is graded to direct stormwater into ditch at North end of Pad.



Photo # 2: North end of pad. Here stormwater flows into reclaim area ditch with no evident BMPs.





Photo # 3: Following from Photo #2 stormwater flows East. No effective BMPs in place.



Photo # 4: Termination of ditch in Photo #3. Wattle is not likely sufficient in itself or installed effectively to control, filter and dissipate energy from such a large surface area.





Photo # 5: Area of Location that has not had Interim Reclamation initiated.