



Photo #1: View from SW corner. Large areas of Location no longer needed for production.



Photo #2: View from SE corner. South end of pad needing stabilizing, reclamation and stormwater maintenance.





Photo #3: View from NW corner. Run-on from Cut slope NW of tank battery



Photo #4 : View from SW corner. Sediment migration from Southern boundary.





Photo #5: Thistle, B list Noxious weed along access road.