



STATE OF  
COLORADO

EnviroScan - DNR, OGCC <dnr\_ogcc.enviroscan@state.co.us>

## Re: Pace 2 Flowline Release

1 message

**Axelson - DNR, John** <john.axelson@state.co.us>

Tue, Aug 25, 2015 at 3:41 PM

To: Bob Parker <rpmindy@msn.com>

Bcc: ogcc.enviroscan@state.co.us

Bob,

Thanks for providing the information. I didn't see anything attached. Do you have any written documentation of the test from the pumper such as gauge readings, pressure chart, start time, stop time, etc.

Thanks,

John E. Axelson, P.G.

East Environmental Supervisor



P 303.894.2100 x5115 | F 303.894.2109 | C 303-916-0527

1120 Lincoln Street, Suite 801, Denver, CO 80203

[john.axelson@state.co.us](mailto:john.axelson@state.co.us) | [www.colorado.gov/cogcc](http://www.colorado.gov/cogcc)

Cc. Complaint #200435406 - Correspondence Texas Tea

On Tue, Aug 25, 2015 at 3:23 PM, Bob Parker <rpmindy@msn.com> wrote:

John, this is to verify that Pace #2 line was tested for leakage on May 14 at 30# for 20 minutes with no loss in pressure by our pumper.

Bob Parker

Sent from my Verizon Wireless 4G LTE smartphone

----- Original message -----

From: "Axelson - DNR, John" <[john.axelson@state.co.us](mailto:john.axelson@state.co.us)>

Date: 07/31/2015 8:53 AM (GMT-07:00)

To: Bob Parker <[rpmindy@msn.com](mailto:rpmindy@msn.com)>

Subject: Re: Pace 2 Flowline Release

Bob,

This is to confirm COGCC receipt of the report. Can you please prepare a basic Form 27 to go along with this. That will allow me to get it entered into our system. You can fill out the top part of the form and state, "see attached report," on the other sections. That would help me a great deal. I'm sure Mr. Braun could do this on your behalf. The Form 27 is not an eForm yet, so you can still pull the pdf off the web site and submit to me as a pdf.

Thanks again,

John E. Axelson, P.G.  
East Environmental Supervisor



P 303.894.2100 x5115 | F 303.894.2109 | C 303-916-0527  
1120 Lincoln Street, Suite 801, Denver, CO 80203  
[john.axelson@state.co.us](mailto:john.axelson@state.co.us) | [www.colorado.gov/cogcc](http://www.colorado.gov/cogcc)

On Fri, Jul 31, 2015 at 9:19 AM, Bob Parker <[rpmindy@msn.com](mailto:rpmindy@msn.com)> wrote:  
John, please find attached report from our consultant.

Bob Parker

Sent from my Verizon Wireless 4G LTE smartphone

----- Original message -----

From: "Axelson - DNR, John" <[john.axelson@state.co.us](mailto:john.axelson@state.co.us)>  
Date: 07/22/2015 4:00 PM (GMT-07:00)  
To: Brandi Parker <[rpmindy@msn.com](mailto:rpmindy@msn.com)>  
Subject: Pace 2 Flowline Release

Bob,

I spoke with Paul Schneider at Anadarko. He said they did not perform any additional cleanup in the open excavation. They provided some pictures that show the excavation is in the same condition as it was last week. They agreed to submit their split sample results that were collected when your consultant performed soil sampling.

Before you replace your flowline section we need to verify that the confirmation samples collected below the release point comply with Table 910-1 standards. Please submit the results of your sampling analysis as soon as you can.

Thank you,  
John

John E. Axelson, P.G.  
East Environmental Supervisor



P 303.894.2100 x5115 | F 303.894.2109 | C 303-916-0527  
1120 Lincoln Street, Suite 801, Denver, CO 80203  
[john.axelson@state.co.us](mailto:john.axelson@state.co.us) | [www.colorado.gov/cogcc](http://www.colorado.gov/cogcc)

