



Photo 1. View of junk and debris within the northern portion of the project area.




Photo 2. View of woody debris within the northern portion of the project area.





Photo 3. View of erosional channel approximately 3 to 4 feet wide and 1.5 feet deep along access road. Stormwater BMPs are needed to de-energize flows along the access road.



Photo 4. View of southern portion of the project area from southwestern corner facing eastward. Vegetation such as intermediate wheatgrass (*Thinopyrum intermedium*), western wheatgrass (*Pascopyrum smithii*), and white fir (*Abies concolor*) are becoming established here.





Photo 5. View of project area from southwestern corner facing center.