



Photo 1. View of erosional channel approximately 2 feet wide and 10 inches deep within northwestern portion of project area. Stormwater flows need to be de-energized here.



Photo 2. View of junk within northwestern portion of project area that needs to be removed.





Photo 3. View of junk within northwestern portion of project area that needs to be removed.



Photo 4. View of northwestern portion of project area from northern corner facing southward. Revegetation is progressing here.





Photo 5. View of vegetated soil stockpile in southern portion of project area.