

## A.P. Urie 1

Inspection# 673402427

Overview of spill area looking east. Breach of berm at base visible in right foreground. Breach of berm with overflow and resultant spill path visible in left background.

Inspection 673402259  
7/20/2015



Overview of spill area looking east. Expanded berm visible, with trace of spill path still visible. Spill material visible in foreground of berm.

Inspection 673402427  
9/2/2015

