



photo 1: Well sign near the location along the access road.



photo 2: Facing north towards the location from the access road.



photo 3: Northeast corner of the location facing southwest towards the location.



photo 4: North side of location facing southeast. Areas no longer needed have not been reclaimed.



photo 5: Northwest side of the location facing south.



photo 6: Northwest side of the location facing south towards soil stockpile.



photo 7: Vegetation growing throughout topsoil pile appears to be mostly weeds (kochia, Russian thistle).



photo 8: Unused equipment at the southeast side of the location.



photo 8: Pipeline south of the location which appears to go to the west. Markers labeled "Bill Barrett".



photo 8: Areas along the pipeline in the pasture south of the location have not been properly reclaimed.



photo 8: Weed growth (kochia) along the pipeline.



photo 8: Surrounding vegetation in the adjacent landowners pasture near the pipeline.