



Photo 1. View of young Canada thistle (*Cirsium arvense*) rosettes within the northern portion of the project area.





Photo 2. View of Musk thistles (*Carduus nutans*) growing outside of eastern edge of revegetation area (in background).



Photo 3. View of Canada thistle infestation outside of project area to the north, from northern edge of well pad facing northwestward. It will be necessary to monitor Canada thistle to prevent further infestation into the well pad area and degradation of desirable revegetation.





Photo 4. View of western portion of interim reclamation area from northwestern corner facing southward. Many desirable species are becoming established.





Photo 5. Birdseye view of grasses becoming established within the interim reclamation area as well as straw mulch. These species were not in identifiable form.





Photo 6. View of well pad and reclamation from northwestern corner facing center.



Photo 7. View of rock armor around culverts that appears to be successfully stabilizing potential erosion in this area.





Photo 8. View of revegetation along the pipeline right of way largely appears to be yellow sweetclover (*Melilotus officinalis*).