

Focus Ranch Unit Federal 12-1

Inspection# 673402453

No sign at wellhead. Lit field flare in background.

9/11/2015

Inspection 673402453



No wellhead sign.

7/28/2014

Inspection 673400900



No tank labels. Incomplete,
uncompacted berm.

9/11/2015

Inspection 673402453



Incomplete, uncompacted
berm. No tank labels.

9/11/2015

Inspection 673402453



No tank labels, no berm.

7/28/2014

Inspection 673400900



Pit work.

9/11/2015

Inspection 673402453



Pit.

7/28/2014

Inspection 673400900



Access road. No stormwater controls for disturbed soil on perimeter. In foreground is completed road, in background is only road base until first switchback turn in far background.

9/11/2015

Inspection 673402453



Newly constructed segment of road. No stormwater controls for disturbed soil. In far background is existing road, moving forward is rough road base only until first switchback turn which is finished road but still without stormwater controls.

9/11/2015
Inspection 673402453



Newly constructed segment of road. Road is incomplete and road base is beginning to migrate off of the road area. No stormwater controls for disturbed soil.

9/11/2015
Inspection 673402453

