



Photo#1: View of location from NW corner.



Photo#2: New BMPs installed where there was serious gully erosion; looking East.



Photo#3: Stormwater controls installed in washout area facing NE.



Photo#4: Culverts installed on North perimeter.



Photo#5: Gravel Pile at NW corner of Location.